

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1203264	display	US-PGPUB; USPAT	ADJ	ON	2008/10/14 10:43
S2	27360755	@ad<"20030807" or @rlad<"20030807"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:44
S3	2683455	display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:45
S4	14330	discharge cell	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:45
S5	7596	clock signal generator	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:45
S6	50	serial data generator	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:45
S7	2705	test signal generator	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:45
S8	5432	phase adjusting	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:46
S9	108	latch failure	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:46
S10	0	S2 and S3 and S4 and S5 and S6 and S7 and S8 and S9	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:46
S11	4750	S2 and S3 and S4	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:46
S12	0	S11 and S7 and S8	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:46
S13	0	S11 and S6	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:47
S14	2	S11 and S5	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:47
S15	89839	plasma display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:48
S16	0	S15 and S2 and S6	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:48

S17	5	S3 and S2 and S6	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:48
S18	6	S15 and S2 and S7	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:49
S19	0	S15 and S2 and S7 and S8	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:50
S20	0	S15 and S2 and (S8 device)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:50
S21	35	S15 and S2 and S8	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:50
S22	0	S15 and S2 and S9	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:54
S23	20	S3 and S2 and S9	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 10:54
S24	262	345/904.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/14 12:28
S25	1	"4839637".pn.	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:40
S26	0	S25 and data generator	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:41
S27	0	S25 and (data same generator)	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:41
S28	0	S25 and (serial same generator)	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:41
S29	0	S25 and serial	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:41
S30	0	S25 and image data	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:45
S31	1	S25 and data	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:45
S32	4	"4839637".pn. or us-20020157033-\$.did. or us-20030214244-\$.did. or us-20020175883-\$.did. or us-2001035862-\$.did.	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:51
S33	5	"4839637".pn. or us-20020157033-\$.did. or us-20030214244-\$.did. or us-20020175883-\$.did. or us-20010035862-\$.did.	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:51
S34	77422	serial near3 data	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:51
S35	0	S33 and S34	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:51

S36	507401	serial	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:51
S37	0	S33 and S36	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:51
S38	11827	data driver	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:51
S39	0	S33 and S38	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:52
S40	82	(phase near3 adjust\$3) and data driver and (serial same data)	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:52
S41	27360753	@ad<"20030807" or @rlad<"20030807"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/15 08:53
S42	82	(phase near3 adjust\$3) and data driver and (serial same data)	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:53
S43	48	S41 and S42	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:53
S44	16	S43 and display	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:53
S45	7	S44 and plasma	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:53
S46	1	us-20020133731-\$.did.	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:58
S47	0	S46 and discharge cells	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:58
S48	0	S46 and clock signal generator	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:58
S49	0	S46 and test signal generator	US-PGPUB; USPAT	ADJ	ON	2008/10/15 08:58
S50	0	S46 and pulse	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:07
S51	41225	plasma near3 display	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:09
S52	1469	(phase adjust\$3) near3 circuit	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:10
S53	29	S51 and S52	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:10
S54	17	S53 and S41	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:10
S55	1	us-20020175883-\$.did.	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:21
S56	1	S55 and discharge	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:21
S57	0	S55 and discharge cell	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:22
S58	1	S55 and discharge	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:22
S59	0	S55 and clock signal generator	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:24

S60	0	S55 and clock near5 generator	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:24
S61	0	S55 and clock with generator	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:24
S62	0	S55 and clock	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:24
S63	0	S55 and (clock or contorl) near3 signal	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:25
S64	1	S55 and (clock or control)	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:25
S65	0	S55 and test	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:26
S66	10	("20010055009" "20020180668" "20060038750" "5451894" "6288699" "6462721" "6501309" "6559603" "6690388" "6927751").PN.	US-PGPUB; USPAT	ADJ	ON	2008/10/15 09:30
S67	4	S66 and discharge cells	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:54
S68	0	S67 and clock signal generator	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:54
S69	0	S67 and clock signal	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:54
S70	0	S67 and clock	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:54
S71	4	S66 and clock	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:54
S72	0	S71 and discharge	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:54
S73	0	S67 and test signal	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:55
S74	0	S66 and test signal	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:55
S75	1	S66 and data driver	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:55
S76	2	S66 and latch	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:55
S77	2	S76 and phase	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:56
S78	0	S76 and phase and discharge	US-PGPUB; USPAT	ADJ	ON	2008/10/15 10:56
S79	10	("20010055009" "20020180668" "20060038750" "5451894" "6288699" "6462721" "6501309" "6559603" "6690388" "6927751").PN.	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:55
S80	4	S79 and discharge cells	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:55
S81	5148	clock signal generator	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:57

S82	4936	S81 and "10"	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:57
S83	0	S81 and S79	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:57
S84	4	S79 and clock	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:57
S85	3	S79 and clk	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:58
S86	0	S79 and clk not S84	US-PGPUB; USPAT	ADJ	ON	2008/10/16 08:58
S87	1	S79 and serial data	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:08
S88	1	S79 and serial near3 data	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:09
S89	1	S79 and serial same data	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:09
S90	1	S79 and serial	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:09
S91	1	S79 and data driver	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:09
S92	3	S79 and drive pulse	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:09
S93	0	S79 and latch failure	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:11
S94	2	S79 and latch	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:11
S95	0	S79 and (latch same failure)	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:13
S96	3	S79 and (phase near3 adjust \$3)	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:13
S97	0	S79 and test signal	US-PGPUB; USPAT	ADJ	ON	2008/10/16 09:24
S98	27361173	@ad<"20030807" or @rlad<"20030807"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:29
S99	108	latch failure	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:29
S100	80	S98 and S99	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:29
S101	2	latch failure detector	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:29
S102	20	S98 and S99 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:30
S103	2310	test signal and serial data	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:31

S104	1028	S103 and display and S98	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:31
S105	79	test signal generator and serial data	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:31
S106	34	S105 and display and S98	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:32
S107	34	detect same (latch near3 failure) and S98	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 09:34
S108	72210	(latch or flip\$1flop) circuit	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 11:09
S109	742	S108 same failure	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 11:09
S110	606	S109 and S98	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 11:09
S111	5	S110 and plasma	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 11:09
S112	2	us-20020140686-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 11:14
S113	1	us-20020140686-\$.did. and latch	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 11:14
S114	1	us-20020140686-\$.did. and latch same failure	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/16 11:14
S115	454358	(clock or time synchroniz\$6)	US-PGPUB; USPAT	ADJ	ON	2008/10/29 12:24
S116	32836	(clock or time) synchroniz\$6	US-PGPUB; USPAT	ADJ	ON	2008/10/29 12:24
S117	27363988	@ad<"20030807" or @rlad<"20030807"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:24
S118	1932	348/175-194.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:47
S119	4170	345/60-72.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:47
S120	4933	345/213,904,204.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:48
S121	543	324/770.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:48

S122	1440	327/158.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:49
S123	876	345/99.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:49
S124	13408	S118 or S119 or S120 or S121 or S122 or S123	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:49
S125	8822	S124 and S117	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:49
S126	359	S125 and S116	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:49
S127	45558	test signal	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:52
S128	149	latch (miss or failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:52
S129	0	S126 and S127 and S128	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:52
S130	16	S126 and S127	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:52
S131	0	S126 and S128	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:52
S132	163	S126 and latch	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:52
S133	1909	latch near5 (miss or failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:53
S134	0	S126 and S133	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:53
S135	0	S126 and (latch same (miss or failure))	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:53
S136	4	S130 and latch	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:53
S137	0	S126 and (flip\$1flop same (miss or failure))	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:54
S138	5	S130 and flip\$1flop	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:56

S139	2655	clock same (phase adjust\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:57
S140	96	S139 and S117 and S124	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:57
S141	63	S140 and (latch or flip\$flop)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:58
S142	9	S141 and (test near3 signal)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:58
S143	7	S126 and (test near3 signal) and (latch or flip\$1flop)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 12:59
S144	0	"10567357" and embodiment	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:14
S145	56	S133 same detector	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:15
S146	49	S145 and S117	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:15
S147	0	S146 and phase adjust\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:15
S148	15	S146 and phase	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:15
S149	0	S146 and (phase near3 adjust \$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:16
S150	0	S146 and (phase same adjust \$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:16
S151	0	S146 and "345"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:16
S152	1	S145 and "345"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:16
S153	4	S146 and ("345"/\$.ccls. or "348"/\$.ccls. or "324"/\$.ccls. or "327"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:18
S154	0	S146 and (700-714/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:21
S155	7	S146 and ("714"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:21

S156	8632	(phase near3 adjust\$) and ("345"/\$.ccls. or "348"/\$.ccls. or "324"/\$.ccls. or "327"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:39
S157	1726	(clock near3 phase near3 adjust\$) and ("345"/\$.ccls. or "348"/\$.ccls. or "324"/\$.ccls. or "327"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:40
S158	389	(clock phase near3 adjust\$) and ("345"/\$.ccls. or "348"/\$.ccls. or "324"/\$.ccls. or "327"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/29 13:40
S159	1	"6501309".pn.	US-PGPUB; USPAT	ADJ	ON	2008/10/30 08:45
S160	0	"6501309".pn. and phase adjust	US-PGPUB; USPAT	ADJ	ON	2008/10/30 08:47
S161	1	"6501309".pn. and phase	US-PGPUB; USPAT	ADJ	ON	2008/10/30 08:47
S162	85184	shift register	US-PGPUB; USPAT	ADJ	ON	2008/10/30 08:58
S163	6068	shift clock	US-PGPUB; USPAT	ADJ	ON	2008/10/30 08:59
S164	13679	phase adjust\$3	US-PGPUB; USPAT	ADJ	ON	2008/10/30 08:59
S165	63	S162 and S163 and S164	US-PGPUB; USPAT	ADJ	ON	2008/10/30 08:59
S166	27364541	@ad<"20030807" or @rlad<"20030807"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 08:59
S167	60	S165 and S166	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 08:59
S168	0	S167 and plasma	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:02
S169	14	S167 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:02
S170	60	S167 and clock	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:17
S171	10	S167 and dll	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:24
S172	28037	serial near3 convert\$3 near3 parallel	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:31
S173	608	S172 and S162 and S163	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:32
S174	575	S173 and S166	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:32

S175	423	S174 and (flip\$1flop or latch)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:32
S176	423	S175 and clock	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:32
S177	201	S176 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:33
S178	2968	S172 same phase	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:33
S179	78	S178 and S162 and S163 and S166	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:33
S180	62	S179 and (flip\$1flop or latch)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:33
S181	62	S180 and phase	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:34
S182	12	S181 and (miss or failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:34
S183	1	"6288699".pn. and phase adjust\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:43
S184	0	"6288699".pn. and serial	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:46
S185	1	"6288699".pn. and parallel	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:46
S186	1	"6288699".pn. and data	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:47
S187	2	"6559603".pn. and plasma	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 09:55
S188	1	"10567357" and open drain	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 10:14
S189	1	"6288699".pn. and MON1	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 10:38
S190	45591	test signal	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 10:49
S191	236	S190 and S164 and S166	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 10:49

S192	40	(S190 same S164) and S166	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 10:49
S193	1	us-20010054924-\$.did. and test signal	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 11:05
S194	1	"10567357" and fields	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 11:16
S195	177	(latch or flip\$1flop) (miss or failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 13:54
S196	133	S195 and S166	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 13:55
S197	6	S195 same detector and S166	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/10/30 13:55
S198	12	"7236147".pn. or "7050022". pn. or "6900781".pn. or "6542135".pn. or "6542135". pn. or "6320326".pn. or us- 20070222710-\$.did. "7244993".pn. or us- 20080036749-\$.did. us- 20080024397-\$.did. 12/236021.app.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:20
S199	2	"7236147".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:21
S200	2	"7050022".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:21
S201	4	"6900781".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:22
S202	2	"6542135".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:22
S203	2	"6542135".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:23
S204	2	"6320326".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:23
S205	2	us-20070222710-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:23
S206	2	"7244993".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:24
S207	2	us-20080036749-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:25

S208	2	us-20080024397-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:25
S209	0	12/236021.app.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:25
S210	0	12/236021	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:25
S211	1	"10567357"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:43
S212	1	"10567357" and logical sum	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 09:43
S213	0	"10567357" and embodiment	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/02 10:09
S214	1	"10567357" and hold	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:32
S215	1	"6288699".pn. and hold	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:33
S216	0	"6288699".pn. and (store or memory)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:33
S217	0	"6288699".pn. and reset	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:35
S218	0	"6288699".pn. and "fig." "7"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:43
S219	0	"6288699".pn. and "fig.7"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:43
S220	0	"6288699".pn. and "fig."	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:44
S221	0	"6288699".pn. and "FIG."	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:44
S222	0	"6288699".pn. and "FIG.7"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:44
S223	0	"6288699".pn. and CLKr	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:44
S224	1	"6288699".pn. and CLK	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:44

S225	1	"6288699".pn. and CKSr	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/04 07:44
S226	523	latch and open drain output	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:18
S227	2403	wired\$1or	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:19
S228	23	S226 and S227	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:19
S229	12	S228 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:19
S230	64	(Flip\$flop or latch) same open drain output	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:21
S231	8	S230 and S227 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:21
S232	0	"6288699"".pn.3"	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:29
S233	2	"6288699".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:29
S234	0	S233 and open drain	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:29
S235	0	S233 and wired\$1or	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:29
S236	9694	logical product	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:40
S237	2341	S236 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:41
S238	1	S237 and S230	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:41
S239	880	S237 and (flip\$flop or latch)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:41
S240	600	S237 and latch	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:41
S241	739	logical product same latch	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:42

S242	152	S241 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:42
S243	2	S242 and wired\$1or	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 07:46
S244	0	S242 and open\$1drain	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:01
S245	520248	(latch or flip\$1flop)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:07
S246	2417	S245 near5 (miss or failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:07
S247	1625	S245 near3 (miss or failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:07
S248	368	S247 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:07
S249	266	S248 and reset	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:08
S250	2068	S245 near5 (failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:08
S251	278	S250 same reset	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:09
S252	84	S251 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:09
S253	1	S233 and (latch or flip\$flop)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:09
S254	1366	S245 near3 (failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:12
S255	168	S254 same reset	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:12
S256	59	S255 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:12
S257	895	S245 near2 (failure)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:14
S258	39	(S257 same reset) and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:14

S259	1	us-20010054924-\$.did. and hold\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:22
S260	0	us-20010054924-\$.did. and hold\$3 and reset	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:27
S263	0	us-20010054924-\$.did. and reset\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 08:35
S264	2	"6097444".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 09:16
S265	1138	exclusive logical sum	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 09:30
S266	256	S265 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 09:30
S267	23	S266 and detection signal	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 09:31
S268	3	S266 and (adjust near3 phase)	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/05 09:37
S269	63	adjust near3 optimal near3 phase	US-PGPUB; USPAT	ADJ	ON	2008/11/05 14:21
S270	9	S269 and display	US-PGPUB; USPAT	ADJ	ON	2008/11/05 14:21
S271	854	detect same (range near3 phase)	US-PGPUB; USPAT	ADJ	ON	2008/11/05 14:28
S272	230	S271 and display	US-PGPUB; USPAT	ADJ	ON	2008/11/05 14:28
S273	61	S272 and (latch or flip\$1flop)	US-PGPUB; USPAT	ADJ	ON	2008/11/05 14:28
S274	2	("20030137482" "20050179628").PN. OR ("7242397").URPN.	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/11/05 14:38
S275	535	(vary near2 phase) near4 clock	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:53
S276	17	S275 and plasma	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:54
S277	15	S276 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:54
S278	263	center near2 range near4 phase	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:56
S279	202665	plasma and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:56

S280	5	S278 and S279	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:56
S281	69	S278 and display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:57
S282	149	S278 and driv\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/06 10:57
S283	3965	((min or minimum) same (max or maximum)) near5 phase	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:01
S284	28080	((min or minimum) same (max or maximum)) same phase	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:01
S285	681420	plasma	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:01
S286	2718468	display	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:01
S287	1032	S284 and S285 and S286	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:01
S288	1032	S287 and (ad<"20030807" or rlad<"20030807")	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:02
S289	709	S287 and (@ad<"20030807" or @rlad<"20030807")	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:06
S290	1346	((min or minimum) same (max or maximum)) near2 phase	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:07
S291	22	S290 and S285 and S286	US-PGPUB; USPAT; EPO; JPO; DERWENT	ADJ	ON	2008/11/19 14:07

11/20/2008 7:32:28 AM

C:\Documents and Settings\jmorris1\My Documents\EAST\Workspaces\10567357.wsp